



EXISTING CONDITIONS

## CLEVELAND PUBLIC LIBRARY SOUTH BRANCH

HBM ARCHITECTS

**HBM**  
ARCHITECTS

EAST FACADE



SOUTH FACADE



WEST FACADE



NORTH FACADE



EXISTING SOUTHWEST CORNER



EXISTING VIEW FROM CLARK AVENUE



EXISTING CONDITIONS

# CLEVELAND PUBLIC LIBRARY SOUTH BRANCH

HBM ARCHITECTS






VIEW FROM OUTDOOR PROGRAM SPACE - NORTHWEST CORNER




STREET VIEW FROM CLARK AVENUE



SECTION DETAIL - ADDITION ENTRY  
 1 1/2" = 1'-0"






EXTERIOR PERSPECTIVE - SOUTHWEST CORNER OF ADDITION

CLEVELAND PUBLIC LIBRARY  
SOUTH BRANCH

HBM ARCHITECTS





EXTERIOR ELEVATION - WEST

CLEVELAND PUBLIC LIBRARY  
SOUTH BRANCH

HBM ARCHITECTS





CLARK AVENUE

SCRANTON ROAD

CLEVELAND PUBLIC LIBRARY  
SOUTH BRANCH

HBM ARCHITECTS

