CLEVELAND PUBLIC LIBRARY

Board Meeting

Safe, Warm and Dry Construction Project

In accordance with the Board resolution adopted on December 21, 2017, a report to the Board of Trustees on direct expenditures for the materials and services as budgeted for the Project and not covered by the GMP and expenditures made from the Owner's Contingency Fund resulting from changes and additions to the Project that have already been made by the Library, and will be made in the future, and which are not included in the GMP, is hereby submitted:

the ratare, and thines are not morated in the contribution.						
For the Period Ending August 31, 2019						
	Safe, Warm and Dry Construction Initiative Budget				\$5,000,000.00	
		<u>E</u> 1	ncumbered		Expended	
URS Corporation - Asbestos Survey and	Testing	\$	-	\$	33,728.21	
Osborn Engineering Company - Professional Architectual and Engineering Services			29,593.78		420,336.22	
Regency Construction Services, Inc Construction Manager at Risk			(0.00)		4,254,062.46	
Direct Expenditures paid from Contingency Fund			28,190.00		62,948.50	
		\$	57,783.78	\$	4,771,075.39	
	Available Budget from Own	ner's	Contingency	and	d Permit Fund	\$171,140.83

		Owner's Contingency and Permit Fund			\$381,871.15
Direct Expenditures					_
<u>Date</u> <u>Vendor</u>	<u>PO</u>	<u>Decription</u>	<u>Er</u>	<u>ncumbered</u>	Expended
11/3/2017 City of Cleveland	171701	Building Plan Processing Fee	\$	-	\$ 3,280.00
		Permits for Glenville, Harvard			
1/22/2018 City of Cleveland	180314	Lee, Lorain and Jefferson		-	 19,256.25
		Permits for Collinwood, Fulton,			
7/15/2018 City of Cleveland	181262	and Langston Hughes		-	18,752.25
		Upgrade/Replace existing			
		indoor wall mount fixtures for			
		Addison Branch that should			
		have been part of Safe, Warm			
10/22/2018 Grainger	181752	and Dry project		-	9,990.00
		Install new fire alarm panel,			
		field devices and 28 zone			
8/16/2019 Siemens Industry, Inc.	191021	intrusion panel at Collinwood		28,190.00	 11,670.00
			\$	28,190.00	\$ 62,948.50

Executed Guaranteed Maximum Price	e (GMP) - Approved by the Board 12/21/18:		\$ 4,425,831.31
Change Orders	Description	<u>Amount</u>	
	Credit for not performing the demo, rework and soil infill of the masonry		
PCO #2 02/21/18	planters at Rockport	\$ (17,122.53)	
PCO #4 02/21/18	Change from wall-hung to floor-mounted water closets at Lorain	(1,191.80)	
PCO #5 02/21/18	Lorain pump changes per the returned submittal	(460.56)	
	Lorain additional work associated with the existing light ballasts located		
PCO #6 02/21/18	in the basement in lieu of light fixtures	2,865.81	
PCO #7 02/21/18	Credit for hand dryers furnished by CPL in lieu of Regency	(3,535.00)	
	Two additional precast concrete bumper blocks at Glenville per the		
PCO #8 02/21/18	returned submittal	252.50	
PCO #9 02/28/18	Additional lighting control to create 4 lighting zones at Glenville	2,038.21	
	Glenville Emergency Lighting: Furnish and install emergency lights that		
PCO #10 02/28/18	are required	1,078.14	
PCO #11 02/28/18	Revisions to electrical panel work at Lorain	(774.67)	
PCO #12 02/28/18	Credit for attaching to basement lights to existing circuit at Lorain	(356.53)	
PCO #13 02/28/18	Complete installation of emergency exit lighting at Lorain	4,672.07	
PCO #14 03/21/18	Replace 1" water valve at Lorain that failed and needed to be replaced	716.09	

Change Orders	Description Additional painting at Lorain behind existing removed light fixtures	<u>Amount</u>
PCO #15 03/21/18	where walls were not painted	1,187.76
PCO #16 03/21/18	Furnish and install materials to repair the Lorain ramp	6,077.71
PCO #17 03/21/18	Added occupancy indicators at Lor, Jeff, and Rock	169.42
PCO #18 03/21/18	Credit for Jefferson thermostats as requested by CPL Replace additional GFCI receptacle on the Glevnille roof that was in need	(1,864.46)
PCO #19 03/21/18	of replacement Revisions for Harvard Lee dorrs/hardware per the returned HL doors,	445.32
PCO #20 03/21/18	frames, hardware submittal	2,578.89
PCO #21 03/21/18	Plumbing camera and investigation work for the sanitary lines completed on 3/6/18 and vent pipe completed on 3/16/18 as requested by CPL	1,483.69
PCO #25 04/10/18	Repair/infill abandoned window opening that was discovered under the exterior ramp during ramp rework	805.84
DCO #2C 04/40/40		1 101 70
PCO #26 04/10/18 PCO #1	Added flashing in the Lorain basement to help water infiltration issues	1,181.70
03/21/18 rec'd 5/14 PCO #22	Alternate #2 Carnegie West restroom configuration option budget pricing	17,546.21
03/28/18 rec'd 5/14	Added check valves at Lorain	755.48
PCO #23	Relocation of two exhaust drops at Glenville that conflicted with the	
03/28/18 rec'd 5/14	toilet partition layout	855.19
PCO #24		
03/28/18 rec'd 5/14 PCO #3	Lorain concrete repairs at exterior storage closet door	3,415.28
02/21/18 rec'd 5/18	Credit for signage manufacturer	(858.50)
Amendment No 2 05/23/18-PCO #33	Eliminate the Rockport Branch from the project (added to Owner's Contingency and Permit fund)	(305,582.46)
PCO #38 05/23/18	Stool costs for infilling the unforescen restroom halo	7,184.13
PCO #39	Steel costs for infilling the unforeseen restroom hole Jefferson Boiler #1 and #2 cleaning/preventative maintenance and	7,184.13
05/30/18	inspection as required by the city inspector	680.74
PCO #40	, , , ,	
05/30/18	Jefferson unit heater demo to accommodate updated restroom layout	680.74
PCO #42	Reimbursement for building permits needed for the Addison Branch and	
05/30/18 PCO #43	Carnegie West Branch	16,649.55
	Modify and reinstall shelving in the Harvard Lee closet that contains	398.92
06/06/18 PCO #44	ductwork per direction of Eric Herman	398.92
06/20/18	The removal of loose brick and patching of the chimney on the roof of the Jefferson Branch	757.50
	Plumbing, drywall, and tile work associated with RFIs 20/22 to repair the	
PCO #27aR	broken Lorain sanitary pipe. Remaining work will be submitted under	447440
04/25/18 rec'd 7/13	PCO 27b. Additional abatement/demo associated with additional LR sanitary work.	14,714.10
PCO #27b	Remove and replace 2nd floor countertop and istall a new mirror. Install	
04/25/18	two cleanouts as requested by CPI	4,922.71
PCO #28		
04/25/18	Revised hardware at Lorain	742.35
PCO #29		
04/25/18	Harvard Lee exit signs and emergency lights per RFI 42	1,324.69
PCO #30	Harvard Lee additional lighting zones per RFI 31 and approved zoning	
05/01/18	suggestion	3,439.45
PCO #31		
05/01/18	Jefferson emergency lights	2,878.50
PCO #32	Classifia listal sections discreted to the DEL con-	220.04
05/01/18	Glenville lintel repair as directed in the RFI response	339.94
PCO #41a		/a 050 :0'
07/11/18	Credit for the elimination of the HL handrails	(1,050.40)
PCO #41b	Reconciliation for the Rockport handrail credit due to an originally	7.057.00
07/11/18	incorrect schedule of values	7,857.80

Change Orders	<u>Description</u>	<u>Amount</u>
PCO #45	Fabrication and installation of aluminum jacketing to insulate two duct	
8/8/18	enclosures and make these ducts weathertight per RFI 69	8,733.47
PCO #46	Furnish and install a new flue though the roof for the existing hot water	
8/7/18	tank at the Addison Branch per RFI 81	678.69

Change Orders	<u>Description</u>	<u>Amount</u>
PCO #47	Light fixtures called out in RFI 79. Lighting not originally called out for	
8/7/18 PCO #48	the ceiling area in the toilet rooms.	2,011.73
8/7/18	Remove and replace caulk and backer rod at the northeast walkway at	225.40
6/7/16	the Jefferson Branch Exploration, excavation and subsequent corrective work at and adjacent	235.40
	to the frost slab at the Jefferson Branch due to an unforeseen pipe.	
PCO #49	Leech beds were added to the ends of the pipe that was uncovered per	
8/7/18	CPL direction	2,140.40
PCO #50		(2.020.00)
8/7/18	Credit for not completing the step crack repair at the Jefferson Branch	(2,020.00)
PCO #51		(454.50)
8/7/18	Credit for not installing the book drop at the Jefferson Branch	(151.50)
PCO #52	Cost to add emergency signs and exit lights back into the Carnegie West	
8/14/18 PCO #55	branch per RFI 90	6,155.99
8/14/18	Cost to install Cornegie West restrange subfloor as directed in DELO2	4 272 20
PCO #56	Cost to install Carnegie West restroom subfloor as directed in RFI 93	4,272.30
8/15/18	Concrete floor infill work and tile patching at the Jefferson Branch due to RFI 65	1,143.32
	Addition of 6 vibration isolators for the rooftop AHU at Carnegie West	1,143.32
PCO #57	per RFI 99. Purchase of vibration isolators was previously approved to	
8/22/18	avoid schedule delays.	3,753.16
PCO #60		
8/22/18	Additional terracotta repair at the Carnegie West Branch per RFI 95	3,787.50
PCO #61	Increasing tuckpointing from 50% to 100% at north and west turret structure at the Langston Hughes Branch per RFI 88. Added sealant	
8/22/18	removal and replacement at the same location	6,344.82
	Core drilling and filling/grouting the sunken slabs to level the sidewalks	
PCO #64	at the Langston Hughes Branch per RFI 109. This price does not include	4 424 70
8/29/18 PCO #66	modification to the existing curb.	4,421.78
8/29/18	Lowering pull stations per the city inspector at the Jefferson Branch.	664.58
PCO #67		004.50
8/29/18	Lowering one fire alarm pull station per RFI 92 at the Carnegie West Branch.	124.23
PCO #68	Lighting controls for lighting zones per RFI 31 for the Carnegie West	12 1.25
8/29/18	Branch	778.44
PCO #69	Modify and re-route the return air duct through the bathroom at the	
8/29/18	Addison Branch per RFI 97	992.12
PCO #72	Furnish and install new soffit in front of existing window to allow for	
08/31/18	installtion of ceiling at 8'6" at the Carnegie West Branch per RFI 106	388.85
	Shift new toilet 3"east to accommodate location of floor joists at the	
PCO #73	Carnegie West Branch per RFI 111. Patching of floor at original location	F4F 40
08/31/18	of the toilet and adjusting wall type "C" to maintain 5'0" turning radius	515.10
PCO #74		1 440 60
08/31/18	Lowering of fire alarm pull stations at the Addison Branch per RFI 92	1,440.60
PCO #58		17 574 00
09/04/18	Cost to seal roof seams at the Carnegie West Branch Remove and replace (9) existing smoke detectors, (1) pull station, and (1)	17,574.00
PCO #71	horn strobe that were not shown in the drawings at Carnegie West per	
09/12/18	RFI 104	7,113.13
DCO #75	Installation of window fiom to the window in the new restroom at	
PCO #75	Carnegie West per RFI 100. Window film to be installed as "3M Fasara	E70 6E
09/19/18 PCO #76	Glass Finish" and the pattern is to be "Frost and Mat Milky White"	570.65
09/19/18	Credit for 2 roof strainers at the Lorain Branch	(101.00)
PCO #77	Resupporting existing to remain ceiling lights that were attached to the	(=02:03)
09/19/18	roof and not properly installed at the Fulton Branch per RFI 122	3,429.70
PCU #78	Latellation of a consultation of the state o	252.50
09/19/18	Installation of one wall hydrant in the men's room per RFI 121	353.50
PCO #79	Final Rockport mechanical credit including mechanical items that were	
09/19/18	able to be returned.	(81,100.98)

Change Orders	<u>Description</u>	<u>Amount</u>
PCO #80	Salvaging and rehanging the women's restroom door at the Addison	
09/19/18	Branch per RFI 116	161.79
PCO #81	Addition of (1) 2" wye strainer before the heating water pumps at the	
09/19/18	Jefferson Branch per punchlist request.	1,551.36
PCO #82	Installation of new ceiling tile and grid in the Men's Restroom an	
09/19/18	Women's Restroom at the Fulton Branch Cleaning quote for Carnegie West requested by Eric Herman. This	1,919.00
	includes washing the interior and exterior windows and frames of the	
PCO #83	skylight, vacuuming all carpet, sweeping and mopping floors and	
09/26/18	cleaning the restroom area	2,020.00
PCO #84	Replacement of damaged storm clean out pipe and fittings at the Fulton	
09/25/18	Branch per RFI 117	895.87
	Roof maintenance reconciliation allowance completed at the Glenville	
	Branch. Roofing work includes the following: strip in all seams and roof	
DCO #0F	curb flashings, clean roof drains, strip in all vent pipes and conduit	
PCO #85	penetrations, infill all pitch pockets with pourable sealer and install walk	(525.20)
09/25/18 PCO #62	pads for a total of \$14,480 of the the \$15,000	(525.20)
08/28/18	Fabrication and installation of 4 pipe reducers at Carnegie West per RFI 80.	526.21
00/20/18	Credit for door 17CW at Carnegie West per RFI 86. RFI 86 called for the	320.21
DCO #CF	installation of a new frame, door and hardware for opening 17CW to be	
PCO #65	removed from the scope of work. Door, frame and hardware material	(202 77)
08/28/18	was turned over the library. Removal and reconstruction of an existing pier at the Addison Branch per	(383.77)
PCO #70	RFI 98. This price includes the removal and reinstallation of 3 light	
10/03/18	fixtures in the pier.	5,476.65
PCO #86	Additional striping requested by Eric Herman at the handicap ramp at	
10/03/18	the Jefferson Branch	505.00
	Additional work and material needed for updated asphalt amount	
PCO #87	needed per RFI 119. Price includes additional 246 square feet of full	2.076.46
10/03/18	depth pavement replacement	3,076.46
PCO #88	Addition of single circuit and 3 wores for a direct tie in for a future door opener at ADA entrance at Carnegie West per RFI 105. Price includes	
10/03/18	painting of conduit to match existing wall color.	850.37
PCO #89	Fabrication and installation of 3 LED wall packs to the exterior back wall	
10/03/18	of the Addison Branch per RFI 114 and Eric Herman's request.	2,542.14
PCO #90	·	·
10/03/18	Providing power to the circulating pumps at Carnegie West per RFI 129	7,387.54
PCO #93	Exit and Emergency lights needed for the restrooms at the Fulton	
10/10/18	Branch.	4,552.03
PCO #95	Additional concrete work requested at the Collinwood Branch including	
10/22/18	removal and replacement of concrete and steel reinforcements.	12,870.43
PCO #96	Provide and install light fixtures for the restroom at Fulton requested in	12,070.13
10/24/18	the RFI 125	1,782.69
	Removal of TruSpun pip and fittings with cast iron pipe and fittings for	•
	the chase vent at the restrooms. Patch and repair walls and ceilings will	
	come out of the interiors patching allowance. A 10 day time extension	
PCO #98	to the substantial completion date is requested due to discovery, pricing, approval and work completion of this piping. This extension is based on	
10/24/18	a 10/23/18 approval	3,620.85
	Additional terracotta repair at Carnegie West. Repairs are	2,020.00
PCO #94	recommended due to cracks, failed/missing mortar and displacement of	
10/29/18	terracotta. Not to exceed price.	9,288.97
PCO #63	Cost for a 3.5'x7'x4" section of concrete pavement at the Glenville	
10/31/18	branch Additional contractors and switching por the lighting zones provided in	488.35
PCO #92R	Additional contractors and switching per the lighting zones provided in RFI 31 for the Collinwood branch. This pricing has been revised to	
		2 505 40
10/31/18	exclude tax that was accidentally included in PCO 92.	3,585.40
10/31/18 PCO #99	exclude tax that was accidentally included in PCO 92. Additional asphalt work requested by the Cleveland Public Library for the	3,585.40

Change Orders	<u>Description</u>	<u>Amount</u>
PCO #100		(200 72)
10/31/18 PCO #101	Credit for the deleted light pole work at the Addison branch per RFI 114	(390.73)
10/31/18	Removal and replacement of the air separator, air vent and expansion tank at Collinwood per RFI 144	2,232.00
PCO #102	•	2,232.00
10/31/18	Demolition of old conduit and wire and replacement with new feeder to AHU-1 at Collinwood per RFI 135	1,363.01
·	Price to demolish tile and drywall and replace tile in the restroom at FL	
PCO #103	due to mold and RFI 117. This price also includes the removal of ACT	
10/31/18	ceiling in the restrooms at Fulton.	697.81
PCO #104		
10/31/18	Price to replace 200 amp disconnect for CU-1 at Collinwood per RFI 136	858.91
PCO #105	Labor and scaffolding costs to change 38 light bulbs at Carnegie West per	
10/31/18	CPL request Touch up painting of the door at Fulton per RFI 131 and Eric Herman	924.27
PCO #106	request. Pricing also includes labor credit for installation of door that	
11/09/18	was deleted.	(39.13)
PCO #107	Replacing the N20s for motor power disconnect at Carnegie West per RFI	
11/09/18	130	136.04
PCO #109		
11/09/18	Mold removal needed in the mechanical room at Fulton.	675.92
PCO #110	Scraping and painting the exterior railings on the west side of Collinwood	
11/09/18	per RFI 137 and 139.	1,262.50
PCO #112	Latellating of a heal flag for the control of a feed of Control of West con-	
11/09/18	Installation of a backflow for the new boiler feed at Carnegie West per RFI 134.	1,085.75
PCO #108		1,005.75
11/14/18	Additional heater and wiring and replacement of the motor starter for the air handling unit at Fulton per RFI 143.	710.02
11/14/10	Labor credit for installing (2) exterior railings on the west side of	710.02
PCO #111	Collinwood per RFI 137 and 139. Railings were ordered previously and	
11/14/18	will be turned over to the library.	(1,756.36)
PCO #113	Labor credit for the installation of the heater that was not needed at	(=======)
11/14/18	Langston Hughes per RFI 120.	(707.00)
PCO #114	Installation of backflow preventer on the water main at Carnegie West	4 600 47
11/14/18	per RFI 134.	1,633.17
PCO #115	Removal and reinstallation of new fuses at Langston Hughes needed per	202.05
11/14/18	city inspector. Rework of the restrooms at Collinwood due to the discovery of tru spun	293.95
PCO #116	piping and RFI 149. Price includes demolition of existing restroom	
11/14/18	features.	6,453.10
PCO #117	Replacement of 5 horn strobe devices to sync with fire alarm system and	
11/14/18	painting patching required at Fulton per RFI 142.	1,506.47
PCO #118		
11/14/18	Budget reconciliation for electrical wire protection at Collinwood that was not needed.	(5,050.00)
	Replace TruSpun Pipe and Fittings with cast iron in the staff bathroom, to	(3,030.00)
PCO #120	the drinking fountain air admittance valve and the front sink pipe in the	
11/26/18	basement.	3,847.09
PCO #122	Replacement of the fiberglass reinforced panel behind the drinking	
11/26/18	fountain at Collinwood.	368.64
	Demolition required as described in RFI 93 for the unforeseen floor grout	
PCO #97	infill that was discovered after tile demolition in the restroom at	
11/28/18	Carnegie West that took place on 8/1 and 8/3.	3,765.28
PCO #119	Additional conduit and motor starters needed for pumps 3 and 4 at	
11/28/18	Collinwood per RFI 153.	3,398.72
PCO #123	Budget reconciliation for ground penetrating radar allowance that was	
11/28/18	not needed.	(3,030.00)
PCO #124	Replacement of the water heater at Collinwood due to poor condition of	
11/28/18	the existing water heater.	557.52

Change Orders	<u>Description</u>	<u>Amount</u>
PCO #125	Additional abatement that took place on 8/28 in the basement at	
11/28/18	Carnegie West due to the shift of toilet per RFI 111	1,761.65
PCO #127	Inspection of VAVs and reconnection of VAVs 3 and 7 at Collinwood.	
12/20/18	Inspection of VAVs took place per Eric Herman's approval.	629.31
PCO #128	Demolition of (2) exhaust drops, installation of (2) new exhaust ducts	
12/20/18	and (3) exhaust grills in the restroom at Collinwood	1,510.54
PCO #138	Repair of an additional lintel on the east elevation that was approved to	2 265 20
12/21/18	be done on time and material basis at Collinwood Credit for not installing the door operator at Lorain that was unable to be	2,265.28
PCO #139	installed due to existing condition space limitations. Door operator was	
12/26/18	turned over to CPL	(204.50)
PCO #130	Fixing the hanging light that was damaged at Fulton due to the previous	
12/27/18	improper connection of the light fixture	144.23
PCO #131		111123
12/27/18	Credit for the tuckpointing of the west elevation of Collinwood that was deleted from the scope per RFI 138	(4,490.46)
PCO #132		(4,430.40)
12/27/18	Credit for the deletion of the replacement of the west entrance	(2.020.10)
	stair/platform at Collinwood per RFI 137	(2,038.18)
PCO #133	Credit for the elimination of clear coat application to (21) Terra Cotta	(4.000.00)
12/27/18	Columns at Carnegie West per owner and architect direction	(1,939.20)
PCO #134	Fixing and maintaining the existing frost slab at Fulton in lieu of replacing	
12/27/18	it per RFI 124	(1,010.00)
PCO #137	Caulking to fill voids in the concrete steps and landing at the west entry and the joint between the asphalt and concrete at the west basement	
12/27/18	stair at Collinwood per RFIs 137 and 139	901.93
PCO #129		
01/08/19	Budget reconciliation for the door closer allowance that was not needed.	(1,313.00)
PCO #136	Caulking at the exterior of the restroom at Fulton to stop and prevent	
01/03/19	further water leakage into the building.	556.50
	<u> </u>	
PCO #140	Additional electrical work required by the electrical inspector at	
01/03/19	Collinwood Reconciliation of drywall patching allowances that was included in the	558.61
PCO #141	Interiors package. Allowance will be reconciled as follows: Carnegie	
01/08/19	West (\$1,896.00), Fulton (\$1,468.65) and Jefferson (\$1,896.00).	(5,313.26)
	Addition of a guardrail to the ramp at Collinwood and painting the	
PCO #135	guardrail per Andy Cygan's bulletin. A temporary guardrail has been	
01/28/19	installed while the permanent guardrail is being fabricated.	3,880.82
PCO #144		
01/25/19	Reconciliation of the temporary HVAC allowance	(4,385.68)
	,	
PCO #142		
01/25/19	Reconciliation of the art protection allowance	(1,443.83)
PCO #142		
01/25/19	Reconciliation of the door rework allowance	(11,417.01)
PCO #145R	Collinwood tile work and reconciliation of window patching allowance.	()
02/11/19	The remainder of tile reconciliation for Fulton is included.	(623.17)
PCO #146R	(2) additional automatic air vents requested by the owner during the	
02/26/19	trainig session at Carnegie West	953.44
	U	
Change Order Number: 010		4-5-
05/29/19	Reconciliation of the contingency	(18,911.58)
	Total Change Orders to date \$	(171,768.84)

Updated Guaranteed Maximum Price (GMP):

\$ 4,254,062.47